



COMPLETION REPORT

1	Name of the work	Construction of RCC drain in Vijayalakshmi layout in ward no. 13		
2	Sanctioned Estimate No. & Date	AA NO: AC/DZ/AA/07/16-17, Dt: 12/05/16. TS NO: CE/DZ/TS/14/16-17, Dt: 16/05/2016.		
3	Head of Account which is chargeable	P-0190		
4	Instrument Order NO. & Date	NO: EE/DD/00/24/16-17, Date: 27/05/2016.		
5	Name Of Contractor	KRIDL.		
6	Time Stipulated for Completion of work			
a				
b	Delay in Exculpation of Work			
7	Measurement recorded in	MB 4163 / P 41624 to 245		
8	Check Measurement of the Asst			
9	Name of the office/official in charge of the work			
10	a) Asst. Eng/junior Eng			
	b) Asst. Exe Engineer			
Sanctioned Estimate Amout		Amount Claims As per Actually Vide As per bills	Excess	Savings
50.00		49.37		

- 1) Certified that the above work has been completed within the stipulated time noted in the
- 2) Certified that the contractor has delayed and completed the work for which necessary fine recovered
- 3) Certified that the above work has been executed by the contractor satisfactory in


 ASSISTANT ENGINEER.


 ಸಹಾಯಕ ಕಾರ್ಯದರ್ಶಿ, ಉಪನಿರ್ದೇಶಕರು
 ಆಸ್ತಿಪಡವಳಿಕೆ, ದಾಖಲಾತಿ ಮತ್ತು
 ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
 ಎಸ್.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು.